



Date: Monday, 30/07/2007 9:10:41 AM
 Use: Linda Lacelle

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D35643
Job Number : 33764	
Estimate Number : 10804	
P.O. Number : N/A	Part Number : D35643
This Issue : 30/07/2007 S.O. No. : N/A	Drawing Number : REWORK
Print Rev. : NC	Project Number : N/A
First Issue : N/A Type : SMALL / MED FAB	Drawing Revision : N/A
Previous Run : 00015	Material : N/A
Written By : 	Due Date : 06/08/2007 Qty: 21 Um: Each
Checked & Approved By : 	
Comment :	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	PACKAGING 1	PACKAGING RESOURCE #1
		
	Comment: PACKAGING RESOURCE #1 remove from stk: 21 x D3564-3 B33244  	
2.0	D35643	WEARSHOE
		
	Comment: Qty.: 1.0000 Each(s)/Unit Total: 21.0000 Each(s) WEARSHOE	
3.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
		
	Comment: SMALL & MEDIUM FAB RESOURCE 1 reform to remove aft joggle  	
4.0	QC5	INSPECT WORK TO CURRENT STEP
		
	Comment: INSPECT WORK TO CURRENT STEP  	
5.0	PACKAGING 1	PACKAGING RESOURCE #1
		
	Comment: PACKAGING RESOURCE #1 re-identify using new B/N  	

Date: Monday, 30/07/2007 9:10:41 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D35643

Job Number: 33764

Part Number: D35643

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

27
D 27/07/30

Job Completion



U 07.07.30

Monday, 30/07/2007 9:10:41 AM
Linda Lacelle

Process Sheet

Spl. 7 2007-30

Customer : CC-DAR01 Dart Aerospace Ltd.
 Job Number : 33764-1
 Estimate Number : 10604
 Job Number : *N/A*
 Job Issue : 30/07/2007 S.O. No. : *N/A*
 Job Rev. : NC
 Job Issue : *N/A* Type : SMALL / MED FAB
 Previous Run : 00015

Drawing Name : D35643
 Part Number : D35643
 Drawing Number : REWORK
 Project Number : *N/A*
 Drawing Revision : *N/A*
 Material : *N/A*
 Due Date : 06/08/2007

Qty: 21 Um: Each

Written By : *[Signature]*
 Checked & Approved By : *[Signature]*
 Comment :

Additional Product



Seq. #: Machine Or Operation:

Description :

1.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
 remove from stk:

21 x D3564-3 B33244

2.0

D35643

WEARSHOE



Comment: Qty.: 1.0000 Each(s)/Unit Total: 21.0000 Each(s)
 WEARSHOE

3.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

reform to remove aft joggle

4.0

CCS

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

5.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

re-identify using new B/N

Monday, 30/07/2007 9:10:41 AM
Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D35643

Job Number: 33764

Part Number: D35643

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

④
2007107130

Completion



U 07-07-30